

Oil Field Environmental Incident Summary

Incident: 20160122104329 **Date/Time of Notice:** 01/22/2016 10:43
Responsible Party: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC
Well Operator: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC
Well Name: HOLTE 161-94-30-31-5MBH
Field Name: STONEVIEW **Well File #:** 32072
Date Incident: 1/22/2016 **Time Incident:** 04:00 **Facility ID Number:**
County: BURKE **Twp:** 161 **Rng:** 94 **Sec:** 30 **Qtr:**
Location Description: Well site

Submitted By: Paul Weddle **Received By:**
Contact Person: Paul Weddle
1200 17TH STREET, SUITE 2200
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine	20	Barrels	20	Barrels		
-------	----	---------	----	---------	--	--

Other

Description of Other Released Contaminant:

brine water used to prevent freezing during stimulation operations.

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

none.

Areal Extent:

on well pad immediately surrounding the frac tanks staged for pending stimulation on the pad.

Potential Environmental Impacts:

none

Action Taken or Planned:

We have a Braun Vac Truck on location during rig up and stimulation activities and it has recovered all of the spilled brine as soon as onsite supervisors were alerted to the spill.

Wastes Disposal Location: Braun Vac Truck will dispose of the brine at a third party disposal facility.

Agencies Involved:

Updates

Date: 1/22/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, was contained to the constructed well site according to the report. NDIC retains oversight.